Compact Pressure Switch


Series ZSE1 (For Vacuum) / ISE1 (For Positive Pressure)

For General Pneumatics





Can be integrated with ZM ejector system.



ZSE ISE

ZSP

PS

ISA

PSE

IS

ISG

ZSM

Variable hysteresis

1 to 10% of set pressure (Variable)


Easy and simple wiring

Connector type



Compact Pressure Switch Series ZSE1/ISE1

How to Order



Output specifications

	Output opcomountions
14	NPN open collector 1 output w/o analog output, 3 turns adjustment
15	NPN open collector 1 output w/o analog output, 200 degrees adjustment
16	NPN open collector 2 output w/o analog output, 3 turns adjustment
17	NPN open collector 2 output w/o analog output, 200 degrees adjustment
18	NPN open collector 1 output w/analog output, 3 turns adjustment
19	NPN open collector 1 output w/analog output, 200 degrees adjustment
55	PNP open collector 1 output w/o analog output, 200 degrees adjustment

With Connector/How to Order

● Without lead wire (Connector 1 pc., Socket 4 pcs.) ··· ZS-20-A

● With lead wire·····ZS-20-5A-□

Note) When ordering switch with 5 m long lead wire, indicate both part numbers.

Ex.) ZSE1-01-15CN----1 pc. ZS-20-5A-50----1 pc.

Lead	d wire length 🕯						
	Nil	0.6 m					
	30	3 m					

5 m

50

Compact Pressure Switch Series ZSE1/ISE1

Specifications


Model		ZSE1	ISE1L	ISE1			
		For vacuum	um For low pressure For h				
Rated pressure range/Set pressure range		0 to -101 kPa	0 to 100 kPa	0 to 1 MPa			
Expanded analog output range		10 to 0 kPa	-10 to 0 kPa	-0.1 to 0 MPa			
Proof pressure		500	1.5 MPa				
Fluid			Air/Non-corrosive, non-flammable gas				
Power supply	voltage		12 to 24 VDC ±10%, Ripple (P-P)10% or less (With power supply polarity protection)				
Current consumption		1 output: 17 mA or less at 24 VDC, 2 output: 25 mA or less at 24 VDC					
Response time		5 ms or less					
Repeatability			±1% F.S. or less				
	Enclosure		IP40				
Operating temperature range			Operating: 0 to 60°C, Stored: -10 to 60°C (With no condensation and no freezing)				
Resistance	Operating humidity ran	ge	Operating/Stored: 35 to 85%RH (With no condensation)				
Vibration resistance		10 to 500 Hz at whichever is smaller of 1.5 mm amplitude or 98 m/s² acceleration,					
	Vibration registance		in X, Y, Z directions for 2 hrs. each (De-energized)				
	Impact resistance		980 m/s² in X, Y, Z directions, 3 times each (De-energized)				
Temperature of	characteristics (Based on	25°C)	±3% F.S. or less				
Withstand voltage		1000 VAC for 1 min. (between live parts and case)					
Insulation resistance		50 MΩ or more (at 500 VDC by megameter) between live parts and case					
Port size		01: R 8, M5 x 0.8 T1: NPTF 1/8, M5 x 0.8 00: ZM ejector mount type					
Mass		40 g (Including 0.6 m-Long lead wire)					
Lead wire Grommet type		Oil-resistant vinyl cabtire code 3 cores, ø3.4, Cross section: 0.2 mm², Insulator O.D.: 1.1 mm					
Load Wile	Connector type		Heat-resistant vinyl electric wire, 4-wire, Cross section: 0.3 mm ² , Insulator O.D.: 1				
Standard		Compliant with CE marking					

Output Specifications

Model	-14	-15	-16	-17	-18	-19	-55
Switch output	NPN open collector 30V, 80 mA			or less		PNP open collector 80 mA or less	
Residual voltage	1V or less (With load current of 80 mA)						
Number of outputs	1 2		1				
Hysteresis	1 to 10% of set	prss. (Variable)	3% F.S. or	less (Fixed)	1 to 10% of set	prss. (Variable)	1 to 10% of set press. (Adjustable)
Indicator light	ON: when output is ON ON: when output is ON		ON: when output is ON				
ilidicator light	(Red) (OUT1: Red, OUT2: Green)		(Red)				
Trimmer adjustment	3 turns	200 degrees	3 turns	200 degrees	3 turns	200 de	egrees
Analog output	None		1 to 5 V \pm 5% F.S. or less (At rated pressure range) 0.6 to 1 V \pm 7% F.S. or less (At set pressure range) Output impedance: Approx. 1 k Ω		None		

Analog output

1 to 5 VDC



Rated pressure range	Α	В	С
For vacuum 0 to -101 kPa	0	-101 kPa	10.1 kPa
For low pressure 0 to 100 kPa	0	100 kPa	-10 kPa
For positive pressure 0 to 1 kPa	0	1 MPa	-0.1 MPa

ZSE ISE

ZSP

PS

ISA

PSE

IS

ISG ZSM


Series ZSE1/ISE1

Calibration Procedure

- Set the ON-pressure by the pressure setting trimmer. Turning clockwise can set the high pressure/high vacuum pressure.
- In the event of setting, use a flat head screwdriver suited for the groove of a trimmer, and rotate it lightly with a fingertip.


¹ SE1(L)-□□-14/-15/-18/-19

- Switches with variable hysteresis can be adjusted by means of the HYS potentiometer in the range 1 to 10% of the setting pressure range.
- Readjust the ON-pressure setting when the hysteresis setting trimmer was changed after setting the ON pressure.




¹₂SE1(L)-□□16/-17

- With pressure setting trimmer 1 (SET 1), OUT
 1 (Black lead wire, Red LED) can be set.
- With pressure setting trimmer 2 (SET 2), OUT 2 (White lead wire, Green LED) can be set.



 Set the possible min. pressure for adsorption confirmation. If setting the pressure lower than that, switch becomes ON in case that adsorption is not completely done. If setting the pressure higher than that, switch does not become ON even though it may absorb workpieces.



Regarding the pressure setting


Observe the following precautions for setting the vacuum pressure:

Use your fingertips to gently turn the screwdriver.

Do not use a screwdriver with a large grip or with a tip that does not fit into the trimmer groove because this could strip the groove.

Hysteresis


Hysteresis is the pressure difference between the ON and the OFF pressure of the output signal. The set pressure is the pressure selected to switch from OFF to ON condition.



How to Use Connector

1. Attaching and detaching connectors


- When assembling the connector to the switch housing, push the connector straight onto the pins until the lever locks into the housing slot.
- When removing the connector from the switch housing, push the lever down to unlock it from the slot and then withdraw the connector straight off of the pin.



2. Crimping of lead wires and sockets

Strip 3.2 to 3.7 mm at the end of the lead wires, insert the ends of the core wires evenly into the sockets, and then crimp with a crimping tool. When this is done, take care that the coverings of the lead wires do not enter the core wire crimping area.

(Crimping tool: model no. DXT170-75-1)




3. Attaching and detaching lead wires with sockets

Attaching


Insert the sockets into the square holes of the connector (with +, 1, 2, – indication), and continue to push the sockets all the way in until they lock by hooking into the seats in the connector. (When they are pushed in their hooks open and they are locked automatically.) Then confirm that they are locked by pulling lightly on the lead wires.

Detaching


To detach a socket from a connector, pull out the lead wire while pressing the socket's hook with a stick having a thin tip (about 1 mm). If the socket will be used again, first spread the hook outward.




Internal Circuit and Wiring Example




¹_zSE1(L)-□ -16, -17



¹_ZSE1(L)-□ -18, -19



¹₇SE1(L)-□ -55



∧ Caution


Be sure to read before handling.
Refer to front matters 58 and 59 for
Safety Instructions and pages 687 to
691 for Pressure Switch Precautions.




Compact Pressure Switch Series ZSE1/ISE1

Dimensions

Grommet type: ZSE1-00-14/-15/-18/-19




Connector type: ZSE1-00-14C/-15C/-18C/-19C




Grommet type: I SE1-01 -14/-15/-18/-19

Pressure setting trimmer




Connector type:


¹/_z SE1-⁰¹/_{T1} -14C/-15C/-18C/-19C



SE1-01-16/-17



SE1-01-16C/-17C



ZSP

PS

ISA

PSE

IS

ISG ZSM